







ADMINISTRATIVE REPORT: MULTI-YEAR CAPITAL AND SCHOOL RENEWAL PROJECT PLAN

BOARD MEETING

January 13, 2021

Purpose

To provide the Board with the Multi-Year Capital and School Renewal Project Plan for the current school year and to make a recommendation for approval.

Background

Starting in 2011-2012 the Board prepared a 10-Year Capital - School Renewal Project Plan (the plan) that is updated each year. The purpose of the plan is to highlight proposed school renewal project activities under the following project types:

Heating/Mechanical Systems Electrical/Lighting
Energy/Controls Communication Systems

Site Improvements Accessibility
Code/Regulatory Small Capital

Security Building Envelope (e.g. Roofing, Windows,

Doors, Structure)

Budget

At the July 13, 2020 Special Board Meeting the 2020-2021 Budget was approved including a capital budget consisting of \$21.1 million in School Renewal funded projects.

 School Renewal
 \$ 4,213,907

 School Condition Improvements
 \$ 16,884,112

 Total
 \$ 21,098,019

The 2020-2021 Budget contained a preliminary plan of proposed renewal projects by category type to highlight how the \$21.1 million would be invested.

In December, the Ministry of Education announced a federal-provincial funding initiative for education-related infrastructure projects recognizing new demands from the effects of COVID-19. This funding may be accessed through an application process for approval in March 2021. The Ministry of Education has nominated \$5.1 million in LDSB qualified projects for federal government



approval.

COVID-19 Resilience Infrastructure Stream (CVRIS) \$ 5,161,500

Current Status

The Facility Services Department has developed the Capital and School Renewal Project Plan based upon the VFA Building Condition reports for all schools; assessing local needs with school staff, analysis from maintenance work orders; knowledge from facilities trades and maintenance staff, and expertise from engineering and other consultants.

The Multi-Year Capital plan includes an updated 2020-2021 listing of \$21,098,019 projects by school or various schools (appendix A). Project work estimates are based upon the best available project scope and costing information at the time of evaluation.

If the COVID-19 Resilience Infrastructure Stream of funding is approved, the projects listed in appendix B will be implemented in the 2020-2021 school year.

CCIA	16.004.112
SCIA	16,884,112
Renewal	4,213,907
Nellewal	
Funding Total	21,098.019
CVRIS	5,161,500
Diamental Comittal Dualinata 2020 2021	
Planned Capital Projects 2020-2021	
B - Building envelope	7,487,000
C - Interiors	527,000
D - Electrical	40,000
D - Lighting	1,446,422
D - ITS	1,251,500
D - HVAC	5,055,026
D - Plumbing	60,000
G - Site	3,182,000
Small Capital	190,000
Planned Project Total	19,238,948
Balance (Contingency)	1,859,071
TOTAL	21,098,019



For the 2021-2022 to 2030-2031 school years, the 10-year plan includes an estimated \$4,500,000 in proposed annual school renewal project activity per year based upon prior year Ministry funding levels. This plan may/will change to reflect actual Ministry school renewal funding levels when announced.

Annual Project Plan for 2021-2022 to 2029-2030

B - Building envelope	1,751,213
C - Interiors	123,266
D - Electrical	9,356
D - Lighting	338,319
D - ITS	292,727
D - Heating	1,182,373
D - Plumbing	14,034
G - Site	744,271
Small Capital	44,441

Estimated School Renewal Total

4,500,000

Recommendations

That the Board:

- Approve the Multi-Year Capital and School Renewal Project Plan.
- That a revised copy of the 10-Year Capital and School Renewal Project Plan be posted on the Board's website.

Prepared by: Craig Young, Superintendent of Business Services

Reviewed by: Krishna Burra, Director of Education

Attachments: Appendix A: 2020-2021 Capital and School Renewal Project Plan Detail

Appendix B: CVRIS Funded Project Details

	Appendix A	
	2020-2021 Capital and School Renewal Project Plan Detail	
School	Project Description	Estimate
Amherst Island PS		
Amherst Island PS	Ventiliation Study	5,180
Amherst Island PS	Phone/PA System Replacement	6,500
Amherstview PS		
Amherstview PS	Ventiliation Study	20,500
Amherstview PS	Drainage Phase 2 Soccer Field	175,000
Amherstview PS	Phone/PA System Replacement	30,500
Bath PS		
Bath PS	Paving	500,000
Bath PS	Phone/PA System Replacement	20,500
Bayridge PS		
Bayridge PS	Paving and Drainage	750,000
Bayridge PS	Lighting and Ceiling Retrofit	54,606
Bayridge PS	Phone/PA System Replacement	22,500
Bayridge SS		
BSS	Flooring	10,000
BSS	CLR Reno - Music room/acoustic improvement review	10,000
BSS	Lighting and Ceiling Retrofit	200,000
BSS	Paving Review/Repair	10,000
BSS	Ventiliation Study	54,606
BSS	Phone/PA System Replacement	64,500
BSS	Roofing	47,000
Calvin Park PS	TOO THE	17,000
Calvin Park PS	Phone/PA System Replacement	15,000
Cataraqui Woods ES	Thone, TY by seem replacement	13,000
Cataraqui Woods ES	Painting	10,000
Cataraqui Woods ES	Ventiliation Study	19,568
Cataraqui Woods ES	Plumbing	10,000
Centennial PS	Tumbing	10,000
Centennial PS	Ventiliation Study	12,614
Centennial PS	Phone/PA System Replacement	15,000
Central PS	Filone/FA System Replacement	13,000
	Eoneina	10,000
Central PS	Fencing	
Central PS	Flooring	10,000
Central PS	Painting	10,000
Central PS	Paving and staircase repair at exterior exit	10,000
Central PS	CLR Reno - Review	10,000
Central PS	Ventiliation Study	11,713
Central PS	Electrical Review	10,000
Centreville PS		
Centreville PS	Fencing	10,000
Centreville PS	Signage	2,000
Clarendon Central PS		
Clarendon Central PS	Phone/PA System Replacement	5,000
Clarendon Central PS	Paving Review/Repair	150,000
Collins Bay PS		
Collins Bay PS	Ventiliation Study	13,812
Collins Bay PS	Phone/PA System Replacement	14,000
Collins Bay PS	Paving Review/Repair	500,000
Elginburg PS		

Elginburg PS	Flooring Replacement	10,000
Elginburg PS	Ventiliation Study	11,536
Enterprise PS		
Enterprise PS	Flooring	10,000
Enterprise PS	Lighting and Ceiling Retrofit	10,000
Enterprise PS	Site Improvement	10,000
Enterprise PS	Phone/PA System Replacement	7,500
Enterprise PS	CCTV	60,000
Enterprise PS	Masonry	10,000
Ernestown SS		
ESS	Lighting Retrofit	139,448
ESS	Phone/PA System Replacement	63,000
ESS	HVAC upgrade - Phase 1	1,100,000
ESS	HVAC upgrade - Phase 2 Controls	670,000
Fairfield ES		
Fairfield ES	AC	55,000
Fairfield ES	Window Coverings	25,000
Fairfield ES	Painting	10,000
Fairfield ES	Swipe Card Access	10,000
Fairfield ES	Windows	350,000
Fairfield PS	Phone/PA System Replacement	20,500
Frontenac SS		
FSS	Front entrance improvement signage, walkway, landscaping, paving revi	30,000
FSS	WR assessment	10,000
FSS	Gym Reno - window replacement, minor repairs, paint	10,000
FSS	Lighting Retrofit	205,087
FSS	Painting	10,000
FSS	CCTV	200,000
Glenburnie PS		
Glenburnie PS	Drainage and curb appeal	10,000
Glenburnie PS	Flooring	10,000
Glenburnie PS	Outdoor classroom/sun shelter	10,000
Glenburnie PS	Window coverings	25,000
Glenburnie PS	Phone/PA System Replacement	13,000
Glenburnie PS	Masonry Project Design	20,000
Granite Ridge Education Centre		
GREC	Phone/PA System Replacement	36,000
Harrowsmith PS		
Harrowsmith PS	Roofing/Windows/Corridor Project	600,000
Harrowsmith PS	Site - traffic barriers	10,000
Harrowsmith PS	Paving	10,000
Harrowsmith PS	Ventiliation Study	13,812
Harrowsmith PS	Phone/PA System Replacement	16,500
JG Simcoe PS		
JG Simcoe PS	Phone/PA System Replacement	11,500
JG Simcoe PS	Paving - Parking Lot / Pedestrian Traffic	300,000
JG Simcoe PS	Painting	10,000
JG Simcoe PS	Windows	10,000
Joyceville PS		,
Joyceville PS	Fencing	10,000
Joyceville PS	Ventiliation Study	11,276
Joyceville PS	Phone/PA System Replacement	13,500
JR Henderson PS		13,300
dilucioon i o		

Marysville PSVentiliation Study2,995Marysville PSBuilding Envelope Assessment10,000Molly Brant ESMolly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education CentreNAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	ID II DC	Discuss /DA Contant Development	26.000
Relenderson PS		·	
R Henderson PS		• •	
IR Henderson PS Painting 10,000 Lancaster Drive PS Roofing 860,000 Land O'Lakes PS Phone/PA System Replacement 12,500 Loyalist Collegiate & Vocational Institute 12,500 LOVI Ughting Retrofit 209,004 LOVI Ughting Retrofit 209,004 LOVI CLR Reno 10,000 LOVI STATALONA PS Molikowa St. Cladding 90,000 Lord Strathcona PS Milliwork 10,000 Lord Strathcona PS Ventiliation Study 12,5			<u> </u>
Lancaster Drive PS Roofing 860,000 Lanca Of Lakes PS Phone/PA System Replacement 12,500 Loyalist Collegiste & Vocational Institute Loyalist Collegiste & Vocational Institute LCVI Phone/PA System Replacement 126,000 LCVI Lighting Retrofit 209,064 LCVI Sports field condition assessment 10,000 LCVI CLR Reno 10,000 Lord Strathcona PS Roof, windows & cladding 90,000 Lord Strathcona PS Painting 10,000 Lord Stra		· · ·	
Lanca Ster Drive PS Roofing 860,000 Land O'Lakes PS Phone/PA System Replacement 12,500 Loyalist Collegiate & Vocational Institute 12,500 Loyalist Collegiate & Loyalist Collegiate & Loyalis		Painting	10,000
Land O'Lakes PS Phone/PA System Replacement 12,500 Loyalist Collegiate & Vocational Institute 12,500 LCVI Uphone/PA System Replacement 126,500 LCVI Uphting Retrofit 209,664 LCVI Sports field condition assessment 10,000 LCVI CLR Reno 10,000 LCVI CLR Reno 10,000 LCVI Window coverings 10,000 LCVI CLR Reno 10,000 LCVI Window coverings 10,000 LCVI Window coverings 10,000 LCVI Window coverings 10,000 LCVI CLR Reno 10,000 LCVI Windows & cladding 900,000 LOVED STATEMORAPS Milliwork 20,000 Lord Strathcona PS Milliwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Use of System Replacement 31,500 Lord Strathcona PS Use of System Replacement 10,000 Loughborough PS Greenh		Destine	900,000
Land O'Lakes PS Phone/PA System Replacement 12,500 Loyalist Collegiate & Vocational Institute 16,000 LCVI Lighting Retrofit 209,064 LCVI Sports field condition assessment 10,000 LCVI CLR Reno 10,000 LCVI Window coverings 10,000 LCVI Window coverings 900,000 Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 200,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Undoor instructional space 45,000 Lord Strathcona PS Undoor instructional space 45,000 Lord Strathcona PS Undoor instructional space 45,000 Lord Strathcona PS Windows 10,000 Lord Strathcona PS Mindows 10,000 Lord Strathcona PS		ROOTING	860,000
Loyalist Collegiate & Vocational Institute 126,000 LCVI Phone/PA System Replacement 126,000 LCVI Lighting Retrofit 209,054 LCVI Sports field condition assessment 10,000 LCVI CLR Reno 10,000 LCVI CLR Reno 10,000 LCVI Window coverings 10,000 LORD STARTACONA PS Roof, windows & cladding 900,000 Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 200,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Windows 400,000 Loughborough PS Windows		Dhana/DA Cushara Danlasarrant	12.500
LCVI Phone/PA System Replacement 126,000 LCVI Lighting Retrofit 299,064 LCVI Sports field condition assessment 10,000 LCVI Painting 10,000 LCVI Window coverings 10,000 LCVI Window coverings 10,000 Lord Strathcoa PS Roof, windows & cladding 900,000 Lord Strathcoa PS Walkway and playground paving 20,000 Lord Strathcoa PS Signage 2,000 Lord Strathcoa PS Painting 10,000 Lord Strathcoa PS Millwork 10,000 Lord Strathcoa PS Ventiliation Study 11,488 Lord Strathcoa PS Ventiliation Study 11,488 Lord Strathcoa PS Outdoor instructional space 45,000 Lord Strathcoa PS Upting/Celling Retrofits 75,000 Lord Strathcoa PS Upting/Celling Retrofits 10,000 Lord Strathcoa PS Windows 400,000 Lord Strathcoa PS Windows 10,000 Loughborough PS Stairs			12,500
LCVI Lighting Retrofit 209,064 LCVI Sports field condition assessment 10,000 LCVI CLR Reno 10,000 LCVI Window coverings 10,000 LCVI Window coverings 10,000 LCVI Window coverings 10,000 LCVI Window coverings 900,000 Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 20,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Undoor instructional space 45,000 Lord Strathcona PS Lighting/Celling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 LSS Partitions - review condition of gym partitions <td></td> <td></td> <td>126 000</td>			126 000
LCVI Sports field condition assessment 10,000 LCVI Painting 10,000 LCVI CLR Reno 10,000 LCVI Window coverings 10,000 LCVI Window coverings 10,000 Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 200,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Ponne/PA System Replacement 13,500 Lord Strathcona PS Ughting/Celling Retrofits 75,000 Lord Strathcona PS Ughting/Celling Retrofits 75,000 Lord Strathcona PS Ughting/Celling Retrofits 10,000		·	
LCVI Paintling 10,000 LCVI CLR Reno 10,000 LCVI Window coverings 10,000 Lord Strathcona PS Work, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 2000,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 Loughborough PS Partitions - WR 15,000 LSS Partition - Feview condit			
LCVI CLR Reno 10,000 LCVI Window coverings 10,000 LOrd Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 20,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Uighting/Celling Retrofits 75,000 Lord Strathcona PS Uighting/Celling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Stairs 100,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 LSS Partitions - WR 15,000 LSS Partitions - WR 15,000 LSS Partition - review condition of g			
LCVI Window coverings 10,000 Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 20,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Stairs 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Partitions - WR 15,000 LSS Partition - Every 10,000 LSS Partition -			
Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 200,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Celling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Loughborough PS			
Lord Strathcona PS Roof, windows & cladding 900,000 Lord Strathcona PS Walkway and playground paving 20,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Uptdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Windows 400,000 Loughborough PS Windows 10,000 Loughborough PS Asia Strate S 10,000 Loughborough PS Stairs 10,000 Loughborough PS Asia Strate S 10,000 Loughborough PS Partitions - WR 15,000 LSS Partitions - WR 15,000 LSS Partil		window coverings	10,000
Lord Strathcona PS Walkway and playground paving 200,000 Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Celling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 LSS Partition - WR 15,000 LSS Partition - WR 15,000 LSS Partition - WR 15,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 <td< td=""><td></td><td>Doof whales of Orderlike a</td><td>000.000</td></td<>		Doof whales of Orderlike a	000.000
Lord Strathcona PS Signage 2,000 Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 LSS Partition Ps Partition Ps Partition Ps Partition Ps Partitions Ps Partitions		-	
Lord Strathcona PS Painting 10,000 Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Loughborough PS Windows 80,000 Loughborough PS Stairs 10,000 Lassalle St Partition - Stype Parti			
Lord Strathcona PS Millwork 10,000 Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Loughborough PS Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 100,000 Lassalle SS LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Partitions - WR 15,000 LSS Partitions - WR 15,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Fire panel replacement 10,000 LSS Fire panel replacement 10,000 LSS Fire panel replacement 10,000 Marysville PS Ventiliation Study 2,995 Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 Molly Brant ES Drainage Review 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000			
Lord Strathcona PS Ventiliation Study 11,488 Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 80,000 Loughborough PS Stairs 80,000 LaSsalle SS Partitions - WR 10,000 LSS Partitions - WR 15,000 LSS Partitions - WR 10,000 LSS Painting - parking lot lines 10,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Structural Review 10,000 LSS Structural Review 2,995 Marysville PS Building Envelope Assessment 10,000 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molty Brant ES Drai			
Lord Strathcona PS Phone/PA System Replacement 13,500 Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Usighting/Ceiling Retrofits 100,000 Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Lasalle SS VI 10,000 LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Parition - review condition of gym partitions 10,000 LSS Price panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Structural Review 10,000 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Courtyard Repair Review 10,000 NAEC			
Lord Strathcona PS Outdoor instructional space 45,000 Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Loughborough PS Seenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 Loughborough PS Stairs 10,000 LaSES Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Partitions - WR 10,000 LSS Partitions - WR 10,000 LSS Partition - Preview Condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 <td></td> <td>·</td> <td></td>		·	
Lord Strathcona PS Lighting/Ceiling Retrofits 75,000 Lough borough PS Greenhouse and garden kitchen 100,000 Lough borough PS Windows 400,000 Lough borough PS Windows 400,000 Lough borough PS Stairs 10,000 Lasalle SS Uses Power PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Partitions - WR 15,000 LSS Partitions - WR 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Fire panel replacement 10,000 Marysville PS Ventilia		·	
Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 LaSalle SS LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Fire panel replacement 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Wentiliation Study 2,995 Marysville PS Ventiliation Study 2,995 Marysville PS Landscaping - Kindergarten rock circle 10,000			
Loughborough PS Greenhouse and garden kitchen 100,000 Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 LaSalle SS LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Structural Review 10,000 LSS Structural Review 10,000 Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 NAEC Courtyard Repair Review 10,000 NAEC Electronic Signage Review 10,000 <		Lighting/Ceiling Retrofits	75,000
Loughborough PS Windows 400,000 Loughborough PS Stairs 10,000 LaSalle SS LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Structural Review 10,000 Marysville PS Structural Review 10,000 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 NOTH Addington Education Center 10,000 NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC E			
Loughborough PS Stairs 10,000 LaSalle SS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Courtyard Repair Review 10,000 NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC <t< td=""><td></td><td>-</td><td></td></t<>		-	
LaSalle SS LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Fire panel replacement 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 LSS Structural Review 10,000 Marysville PS Marysville PS Marysville PS Marysville PS Marysville PS Mulding Envelope Assessment 10,000 Molly Brant ES Molly Brant ES Molly Brant ES Drainage Review 10,000 North Addington Education Centre NAEC Courtyard Repair Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Painting - Second floor refurbishment 10,000			
LSS Phone/PA System Replacement 80,000 LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 North Addington Education Centre NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Front entrance Improvements 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Painting - Second floor refurbishment 10,000 <td></td> <td>Stairs</td> <td>10,000</td>		Stairs	10,000
LSS Partitions - WR 15,000 LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 North Addington Education Centre NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Front entrance Improvements 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Painting - Second floor refurbishment 10,000			
LSS Roofing 1,000,000 LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 NOTH Addington Education Centre 10,000 NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Front entrance Improvements 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000		·	80,000
LSS Painting - parking lot lines 10,000 LSS Partition - review condition of gym partitions 10,000 LSS Controls - Lighting exterior 10,000 LSS Fire panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Front entrance Improvements 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Painting - Second floor refurbishment 10,000		Partitions - WR	
LSSPartition - review condition of gym partitions10,000LSSControls - Lighting exterior10,000LSSFire panel replacement10,000LSSStructural Review10,000Marysville PSMarysville PSVentiliation Study2,995Marysville PSBuilding Envelope Assessment10,000Molly Brant ESMolly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education Centre10,000NAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000		Roofing	1,000,000
LSSControls - Lighting exterior10,000LSSFire panel replacement10,000LSSStructural Review10,000Marysville PSMarysville PSVentiliation Study2,995Marysville PSBuilding Envelope Assessment10,000Molly Brant ESMolly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education Centre10,000NAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPaving - Second floor refurbishment10,000	LSS	Painting - parking lot lines	10,000
LSS Fire panel replacement 10,000 LSS Structural Review 10,000 Marysville PS Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 North Addington Education Centre NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Front entrance Improvements 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Painting - Second floor refurbishment 10,000		Partition - review condition of gym partitions	•
LSS Structural Review 10,000 Marysville PS Marysville PS Ventiliation Study 2,995 Marysville PS Building Envelope Assessment 10,000 Molly Brant ES Molly Brant ES Landscaping - Kindergarten rock circle 10,000 Molly Brant ES Drainage Review 10,000 North Addington Education Centre NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Front entrance Improvements 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Painting - Second floor refurbishment 10,000			
Marysville PSMarysville PSVentiliation Study2,995Marysville PSBuilding Envelope Assessment10,000Molly Brant ESMolly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education CentreNAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000			
Marysville PSVentiliation Study2,995Marysville PSBuilding Envelope Assessment10,000Molly Brant ESMolly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education CentreNAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	LSS	Structural Review	10,000
Marysville PSBuilding Envelope Assessment10,000Molly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education CentreNAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	Marysville PS		
Molly Brant ESMolly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education CentreNAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	Marysville PS	Ventiliation Study	2,995
Molly Brant ESLandscaping - Kindergarten rock circle10,000Molly Brant ESDrainage Review10,000North Addington Education CentreNAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	Marysville PS	Building Envelope Assessment	10,000
Molly Brant ESDrainage Review10,000North Addington Education CentreNAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	Molly Brant ES		
NAEC Courtyard Repair Review 10,000 NAEC Drainage Review 10,000 NAEC Electronic Signage Review 10,000 NAEC Front entrance Improvements 10,000 NAEC Paving - Parking lot/play areas (drainage and lighting) 10,000 NAEC Painting - Second floor refurbishment 10,000	Molly Brant ES	Landscaping - Kindergarten rock circle	10,000
NAECCourtyard Repair Review10,000NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	Molly Brant ES	Drainage Review	10,000
NAECDrainage Review10,000NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	North Addington Education Cen	tre	
NAECElectronic Signage Review10,000NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	NAEC	Courtyard Repair Review	10,000
NAECFront entrance Improvements10,000NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	NAEC	Drainage Review	10,000
NAECPaving - Parking lot/play areas (drainage and lighting)10,000NAECPainting - Second floor refurbishment10,000	NAEC	Electronic Signage Review	10,000
NAEC Painting - Second floor refurbishment 10,000	NAEC	Front entrance Improvements	10,000
<u> </u>	NAEC	Paving - Parking lot/play areas (drainage and lighting)	10,000
NAEC Masonry Review 10,000	NAEC	Painting - Second floor refurbishment	10,000
	NAEC	Masonry Review	10,000

NAEC	Phone/PA System Replacement	48,000
Napanee District SS		
NDSS	CLR Reno Review - School to Community C12	10,000
NDSS	Curb appeal review - painting front of school	10,000
NDSS	Gymnasium condition review	10,000
NDSS	Lighting Retrofit	317,831
NDSS	Roofing	17,500
Odessa PS		·
Odessa PS	CLR Reno	40,000
Odessa PS	Ventiliation Study	19,996
Odessa PS	Phone/PA System Replacement	23,500
Perth Road PS	, ,	,
Perth Road PS	Landscaping - curb appeal, sight lines	10,000
Perth Road PS	Phone/PA System Replacement	18,500
Polson Park PS		
Polson Park PS	Painting	10,000
Polson Park PS	Ventiliation Study	12,893
Polson Park PS	Whiteboards	10,000
Prince Charles PS	· · · · · · · · · · · · · · · · · · ·	10,000
Prince Charles PS	Repair soffits	10,000
Prince Charles PS	Roofing	550,000
Prince Charles PS	HVAC	465,000
Prince Charles PS	Phone/PA System Replacement	15,500
RG Sinclair PS	Filolie/FA System Replacement	13,300
RG Sinclair PS	Phone /DA System Penlacement	15 500
RG Sinclair PS	Phone/PA System Replacement Roofing	15,500
Rideau Heights PS	nooning	17,500
Rideau Heights PS	Pailar Panlacament	700.000
Rideau Heights PS	Boiler Replacement Roofing	790,000
	9	17,500
Rideau Heights PS Rideau PS	Phone/PA System Replacement	23,000
	Flancina	20,000
Rideau PS Rideau PS	Flooring	30,000
Rideau PS	Painting Reiler Payloroment	10,000
	Boiler Replacement	980,000
Rideau PS	Electrical - Fire Alarm Panel Replacement	1 000 000
Rideau PS	Roofing & Cladding	1,000,000
Selby PS	Variant interior/autorian	10.000
Selby PS	Keying - interior/exterior	10,000
Selby PS	Phone/PA System Replacement	15,000
Sydenham HS		40.000
SHS	Flooring Replacement	10,000
SHS	Front Entrance - improvement review	10,000
SHS	Lighting Retrofit	164,705
SHS	Masonry - Bell Tower	10,000
SHS	Millwork	30,000
SHS	Site - North Entrance Accessibility Project	620,000
SHS	Whiteboard Replacement	10,000
SHS	Window Coverings	10,000
SHS	Shop Reno - Manufacturing Shop	125,000
SHS	Phone/PA System Replacement	65,500
Sir John A. MacDonald ES		
Sir John A. MacDonald ES	Phone/PA System Replacement	46,000
Sir John A. MacDonald ES	Kindergarten exit walkway repair	10,000

Sir John A. MacDonald ES	Outdoor naturalization and yard improvement review	30,000
Southview PS		
Southview PS	Roof Access - Ladder	10,000
Southview PS	Painting	10,000
Southview PS	Plumbing	10,000
Southview PS	Parking lot barriers	10,000
Southview PS	Sports field repair	20,000
Southview PS	Window repair review	10,000
Storrington PS		
Storrington PS	Ventiliation Study	10,720
Sydenham PS		
Sydenham PS	Line painting and site improvement review	10,000
Sydenham PS	Millwork	10,000
Sydenham PS	Ventiliation Study	10,720
Sydenham PS	Access - swipe card entry	10,000
Sydenham PS	HVAC	10,000
Sydenham PS	Partitions - WR	10,000
Tamworth ES		
Tamworth ES	Flooring	10,000
Tamworth ES	Plumbing	10,000
Tamworth ES	Door replacement	10,000
Tamworth ES	PA System Replacement	10,000
Tamworth ES	Windows	10,000
Tamworth ES	Phone/PA System Replacement	11,500
The Prince Charles PS		
The Prince Charles PS	Library Reno	150,000
The Prince Charles PS	Roofing	700,000
The Prince Charles PS	Windows and Masonry	10,000
The Prince Charles PS	HVAC	600,000
The Prince Charles PS	Phone/PA System Replacement	28,000
Truedell PS		
Truedell PS	Site Improvement - Play Surfaces and Shade Structures	30,000
Truedell PS	Fencing	10,000
Truedell PS	Painting - Exterior	10,000
Truedell PS	Roofing	17,500
Truedell PS	Windows	10,000
Truedell PS	Phone/PA System Replacement	15,500
WJ Holsgrove PS		
WJ Holsgrove PS	Phone/PA System Replacement	10,000
Welborne ES		
Welborne ES	CLR Reno - Library dividing wall	10,000
Welborne ES	Gym Floor Replacement	60,000
Welborne ES	Phone/PA System Replacement	23,000
Winston Churchill PS		
Winston Churchill PS	Accessibilty - HC door operators - swipe access	10,000
Winston Churchill PS	Fencing and Gates	10,000
Winston Churchill PS	Water Filling Station	10,000
Winston Churchill PS	Parking Lot Project	210,000
Winston Churchill PS	Ventiliation Study	16,597
		20,007

Appendix B

Projects Nominated for - Federal COVID-19 Resilience Infrastructure Stream Funding (CVRIS)

School	Project Description	Planned	Estimate
Amherstview PS	Network Connectivity	\$	5,000
Bayridge PS	Entrance and Security Enhancements	\$	100,000
BSS	CCTV	\$	200,000
Cataraqui Woods ES	Portable Replacement	\$	100,000
ESS	HVAC Project	\$	600,000
Fairfield ES	HVAC Project	\$	400,000
GREC	HVAC Project	\$	100,000
Harrowsmith PS	Network Connectivity	\$	2,500
JG Simcoe PS	HVAC Project	\$	125,000
JR Henderson PS	Network Connectivity	\$	2,500
JR Henderson PS	Entrance and Security Enhancements	\$	60,000
Land O'Lakes PS	HVAC Project	\$	500,000
LCVI	Network Connectivity	\$	50,000
Loughborough PS	Network Connectivity	\$	50,000
LSS	Network Connectivity	\$	50,000
NAEC	CCTV	\$	200,000
NDSS	CCTV	\$	200,000
Perth Road PS	Entrance and Security Enhancements	\$	300,000
Perth Road PS	Classroom Partition - curtains	\$	75,000
Polson Park PS	Network Connectivity	\$	10,000
Polson Park PS	Portable Replacement	\$	100,000
Prince Charles PS	Network Connectivity	\$	5,000
Rideau Heights PS	Entrance and Security Enhancements	\$	50,000
Selby PS	HVAC Project	\$	330,000
SHS	Network Connectivity	\$	10,000
The Prince Charles PS	ССТУ	\$	99,000
The Prince Charles PS	HVAC Project	\$	750,000
The Prince Charles PS	Entrance and Security Enhancements	\$	60,000
Truedell PS	HVAC Project	\$	400,000
WJ Holsgrove PS	Network Connectivity	\$	2,500
WJ Holsgrove PS	Entrance and Security Enhancements	\$	50,000
WJ Holsgrove PS	HVAC Project	\$	175,000